



0044

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

February 3, 1988

TO: John Whitehead, Permit Supervisor

FROM: Pamela Grubaugh-Littig, Reclamation Engineer *pgl*

RE: Trail Mountain Mine-Second Mining East of Escarpment,  
Submitted January 28, 1988, Beaver Creek Coal Company,  
ACT/015/009-88A, Folder #2, Emery County, Utah

I reviewed the submittal received January 28, 1988 from Beaver Creek Coal Company for second mining east of the escarpment. This submittal lacks basic information.

1. The exact location of the limited pillar extraction should be depicted clearly on Plate 3-6.
2. The method and configuration of shaving (or altering the pillars) should be shown (before and after drawings).
3. The November 14, 1985 study entitled Appendix 12-1 "Limited Second Mining of Areas East of Escarpment" repeatedly refers to Plate I. Plate I must be submitted to fully understand the study.

Additionally, there are careless errors in the submittal that must be corrected.

- Page 3 of Chapter 3, Tract II (as shown in the January 28, 1988 submittal) is a page that continues from a preceding page. However, this makes no sense because page 2 of Chapter 3, Tract II does not continue.
- The power system description on page 3 of Chapter 3 of Tract II is completely deleted from the text. Please correct these errors.
- The description of the barrier pillars on the revised page 3 refers to Figure 5-6, which does not exist. Please correct and clarify.

Upon submittal of this basic and corrected information, a technical review can proceed.

djh  
9075R/40