



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

March 11, 1991

TO: Pamela Grubaugh-Littig, Permit Supervisor

FROM: Jesse Kelley, Reclamation Engineer *JK*

RE: Operator Response to Division Order Requiring Delineation of Pre-1977 Disturbances on Mine Maps, Beaver Creek Coal Company, Trail Mountain #9 Mine, ACT/015/009, Folder #~~3~~, Emery County, Utah
2

Synopsis

On December 17, 1990, the Division issued a Division Order to the Permittee. The Division Order found that the Mining and Reclamation Plan (MRP) was in contravention of R614-301-142 in that the maps contained in the MRP did not delineate those areas which were disturbed prior to August 3, 1977. The Division Order further ordered the Permittee to comply with R614-301-142 by correcting the maps.

On February 25, 1991, the Permittee submitted corrected maps to the Division for its approval.

Analysis

The corrected maps are 3-1 (Surface Facilities), 3-12 (Post Mining Contour Map-Reclamation Phase I), and 3-12A (Post Mining Contour Map-Reclamation Phase II). The corrected maps all clearly and adequately show the boundaries of all areas disturbed prior to August 3, 1977 and are, therefore, in compliance with R614-301-142.

Recommendation

It is recommended that the permit changes mandated by the Division Order be approved and that the corrected maps be inserted into the MRP.

jbe
AT015009.002