



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten signature/initials

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: ___ Exploration: ___
Inspection Date & Time: 30 July 1993 10:00 to 15:00
Date of Last Inspection: 2 June 1993

Mine Name: Trail Mountain County: Emery Permit Number: ACT/015/009
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005 Huntington, Utah 84528
Type of Mining Activity: Underground X Surface ___ Prep. Plant ___ Other ___
State Officials(s): Jess Kelley
Company Official(s): Karl Housekeeper, Dale Grange
Federal Official(s): None
Weather Conditions: Sunny and hot
Existing Acreage: Permitted- 1450 Disturbed- 9.85 Regraded- ___ Seeded- ___ Bonded- 9.85
Increased/Decreased: Permitted- ___ Disturbed- ___ Regraded- ___ Seeded- ___ Bonded- ___
Status: ___ Exploration/ X Active/ ___ Inactive/ ___ Temporary Cessation/ ___ Bond Forfeiture
Reclamation (___ Phase I/ ___ Phase II/ ___ Final Bond Release/ ___ Liability ___ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 30 July, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS & MARKERS

Disturbed area boundary markers were observed. The permittee was advised to paint the existing markers and place additional markers in the area of the sediment pond in order to better define the disturbed area boundary.

4. HYDROLOGIC BALANCE

a) **Diversions**--All diversions and culverts were observed, including the sediment pond inlet structure. All were found to be clean and in good repair. As equipment and parts are being brought from the mine, the permittee is advised to take special care not to block the diversions.

b) **Sediment Ponds and Impoundments**--The sediment pond contained very little water and had not discharged since the last inspection. Sediment pond embankments support a light cover of vegetation and are in good repair.

c) **Other Sediment Control Measures**--Silt fences on the topsoil stockpile, in the BTCA at the upper end of the site, and in the BTCA below the sediment pond were examined and found to be clean and in good repair.

16. ROADS

a) **Construction/Maintenance/Surfacing**--All roads and pads have been surfaced with gravel. The gravel is working very well to prevent erosion and fugitive dust.

19. AVS CHECK

PacifiCorp is listed as the permittee on all documents.

Copy of this Report:

Mailed to: Bernie Freeman/OSM; Karl Housekeeper/PacifiCorp

Given to: Joe Helfrich (DOGM); Price Field Office (DOGM)

Inspector's Signature: _____

Jesse W. Kelley

#34 Date: 8/2/93