



op page

inspection report

Partial Inspection Date: June 2, 1993
 Complete Time: 9 :00 am pm to 1 :30 am pm
 Exploration Date of Last Inspection: 2/15/93

Mine Name: Trail Mtn County: Emery Permit Number: Act 015/009
 Permittee and/or Operator's Name: Pacifi Corp
 Business Address: P.O. Box 1005, Huntington, Utah 84528
 Type of Mining Activity: Underground Surface Prep. Plant Other
 State Official(s): Bill Malencik
 Company Official(s): Karl Hauskeeper
 Federal Official(s): N/A
 Weather Conditions: Cloudy / Cool / Dry Mine Site
 Existing Acreage: Permitted-1450 Disturbed-985 Regraded- Seeded- Bonded-985
 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
 Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. <u>Other</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 6/2/93

Please number comments to correspond with topics on previous page.

General Comments. Partial inspection concentrated on the field environmental control measures. After the field inspection, returned to mine office and reviewed the records on approved disturbed areas where runoff does not drain to a pond. The records are complete, the operator has responded to Division concerns, and runoff from such areas are treated with other sediment control measures.

The mine as of May 1993 is again on active status.

Diversions. The disturbed and undisturbed culverts, ditches, berms & other runoff conveyance systems were checked.

Sediment Pond. Sediment pond contained runoff, was not discharging and was about 3 feet below the decant level. No mine water was being discharged into the pond during the inspection.

Other Sediment Control. Silt fences on the topsoil pile and the upper BTCA area were observed and no problems were observed as related to the effectiveness of such control measures.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____

No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 6/2/93

Please number comments to correspond with topics on previous page.

Roads. The primary road and parking areas were
graveled since the undersigned made the
last inspection.

Support Facilities. The loading dock and storage
facility, new additions approved by the Division,
are currently being measured and included
on a revised Surface facilities map.

Mr. Housekeeper stated the updated map
should be sent to the Division as soon
as the measurements and surveying is
completed.

Other. The irrigation water diversion and parcell
flume associated with the Peacock farm was
observed. The weir reading was 1.14'.

Copy of report mailed to

PC/Karl Housekeeper; OSM/Petta; DOGM/Heltrich

Copy of report given to

filed PFO

Inspector's signature

Mr. J. Chalovich

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITEE/OPERATOR GOLDENROD - NOV FILE

6/3/93