



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 2/22/94 10 TO 12
Date of Last Inspection: 1/18/94

Mine Name: Trail Mountain County: Emery Permit Number: ACT/015/009
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005, Huntington, Utah 84528
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Susan White
Company Official(s): Karl Housekeeper
Federal Official(s): None
Weather Conditions: Cold and windy
Existing Acreage: Permitted-1450 Disturbed-24.8 Regraded- Seeded- 0 Bonded-24.8
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 2/22/94

(Comments are Numbered to Correspond with Topics Listed Above)

The site was covered with about a foot of snow. Currently the mine is not producing coal but being updated to accommodate long wall mining. Mining will probably not commence until 1995 assuming the two entry mining method is approved.

#### 4. HYDROLOGIC BALANCE:

a. Diversions - The diversion through the bottom gate requires immediate maintenance. The second gate will need maintenance in the spring.

#### 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES

"Excess" fill material from the construction and upgrading of facilities is scheduled to be disposed at the Cottonwood Waste Rock facility. This activity is authorized in the permit. However, the permit states that there is insufficient material on site to achieve original contour in reclamation. Therefore, it appears to this inspector that there is no excess fill and all fill (quantities are small) should remain on site or in an area to be retrieved during final reclamation.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Karl Housekeeper (PacifiCorp)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Susan M. White* #35 Date: 2/24/94