



inspection report

- Partial
- Complete
- Exploration

Inspection Date: August 10, 1995
 Time: 8 : 00 am pm to 3 : 00 am pm
 Date of Last Inspection: 7/13/95

Mine Name: Trail Mtn County: Emery Permit Number: Act 015/009
 Permittee and/or Operator's Name: Pacifi Corp/Energy West
 Business Address: P.O. Box 1005, Huntington, UT 84528
 Type of Mining Activity: Underground Surface Prep. Plant Other
 State Officials(s): Bill Malencik
 Company Official(s): Karl Houskeeper
 Federal Official(s): N/A

Weather Conditions: Pt Cloudy
 Existing Acreage: Permitted- 1450 Disturbed- 248 Regraded- _____ Seeded- _____ Bonded- 248
 Increased/Decreased: Permitted- _____ Disturbed- _____ Regraded- _____ Seeded- _____ Bonded- _____
 Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability _____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 8/10/95

Please number comments to correspond with topics on previous page.

General Comments. The instant partial inspection concentrated on 1994 exploration on Trail Mountain. Also, observed ongoing construction activities and environmental control measures associated with recent approved amendments at the mine site, Mine.

• Other sediment control. Silt fences provide sediment control on the ASCA above the parking lot. The construction and reconstruction activities are all taking place on the existing approved disturbed area. The drainage from this area drains to the sediment pond.

• Support facilities.

• The overhead 12 1/2' steel tube to accommodate the coal transportation beltline and other items was in place. The tube was erected the prior weekend.

• The vehicle portal was faced up since the last inspection ^{at Cottonwood.}

• The chain link fence was removed to accommodate the erection of the steel tube. Only part of the fence was removed i.e., the entire fence where it would impede the steel tube project. The fence needs to be reinstalled when construction is completed.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 8/10/95

Please number comments to correspond with topics on previous page.

Exploration Observed the following:

- (1) Road that was blocked last fall has now been reopened. Suggest the sign that was erected now be removed, since the current language doesn't fit the field situation, or change the language.
- (2) The drill pad near the road closure sign had a good grass cover, some folks did not observe many browse plants. It's my opinion it's premature to make a final seeded species evaluation comparing seeded and established plants.
- (3) Roads were recently graded to the exploration site.
- (4) The 1995 exploration planned for this summer has not started.

Copy of report mailed to PC/Karl Houskeeper; OSM/Donna Guffin; DOGM/Joe Helfrich

Copy of report given to filed PFO

Inspector's signature Jim J. Chalovich No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

8/14/95