



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:

Company Chuck Semborski Environmental Supervisor

Inspection Report

Permit Number:	C0150009
Inspection Type:	COMPLETE
Inspection Date:	Thursday, March 04, 2004
Start Date/Time:	03/04/2004 8:40:00 AM
End Date/Time:	03/04/2004 1:00:00 PM
Last Inspection:	Monday, December 08, 2003

Inspector: Pete Hess, Environmental Scientist III

Weather: Cold; cloudy; some flurries

InspectionID Report Number: 194

Accepted by: dhaddock
 03/09/2004

Permittee: **PACIFICORP**
 Operator: **ENERGY WEST MINING CO**
 Site: **TRAIL MOUNTAIN MINE**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

3,539.00	Total Permitted
10.69	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The site remains in temporary cessation status. The Mine site is covered by deep snow, ranging in the depth from eighteen to twenty inches. Although temperatures have been warmer than those experienced during January and February, many of the buildings have heavy snow loads on their roofs. All access to the site was barred by frozen compacted snow around the gates.

Inspector's Signature: _____

Date Friday, March 05, 2004

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
Where ideas connect™

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
 - a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
 - b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

4.a Hydrologic Balance: Diversions

All diversions were buried under snow, and were incapable of being inspected.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

As viewed from the disturbed area fence, the mine site sediment pond was covered by deep snow. There were no problems evident. The permittee conducted the fourth quarter impoundment inspection for the Trail Mountain mine site sediment pond on December 9, 2003. There were no unstable or structural weaknesses noted by the inspection performed by Messrs. John Christensen and Rick Cullum. The pond was noted as being frozen over, with no discharge from the UPDES outfall 001A. The surveyed sediment storage volume remaining was noted to be 0.19 acre-feet. Mr. Christensen performed a P.E. certification of the inspection report on December 31, 2003.

4.c Hydrologic Balance: Other Sediment Control Measures

Both alternate sediment control areas are under deep frozen snow; inspection of the treatment methods was not possible.

4.d Hydrologic Balance: Water Monitoring

The following water monitoring sites relative to the Trail Mountain permit area were monitored for flow during the months of January and February; T-19, SW-1, SW-2 and SW-3. To date, water monitoring information for the fourth quarter of 2003 is still being loaded into the Division's electronic web site.

14. Subsidence Control

The permittee was in the process of preparing the 2003 annual subsidence monitoring report for submittal with the annual report this day. MapCon Aerial Surveys of Salt Lake City conducted the flyover of the Trail Mountain permit area on September 14, 2003.

15. Cessation of Operations

As noted above, the site remains in temporary cessation status.

21. Bonding and Insurance

The permittee's current general liability insurance remains in effect until April 1, 2004. Mr. Semborski is aware of this and intends to have continued coverage in place prior to the termination of the current policy period.

Permit Number: C0150009
Inspection Type: COMPLETE
Inspection Date: Thursday, March 04, 2004

22. Other

It is the Division's intent to revise the current inspection schedule for this site so that a complete inspection of the Mine site can be made as soon after snow melt has occurred as possible in order to evaluate necessary spring maintenance. Mr. Semborski was made aware of the proposed revised inspection schedule.