



The State of Utah
 Department of
 Natural Resources
 Division of
 Oil, Gas & Mining

ROBERT L. MORGAN
 Executive Director

LOWELL P. BRAXTON
 Division Director

OLENE S. WALKER
 Governor

GAYLE F. McKEACHNIE
 Lieutenant Governor

Representatives Present During the Inspection:	
Company	Dennis Oakley Environmental Engineer
OGM	Pete Hess Environmental Scientist III

Inspection Report

Permit Number:	C0150009
Inspection Type:	PARTIAL
Inspection Date:	Friday, April 09, 2004
Start Date/Time:	04/09/2004 10:00:00 AM
End Date/Time:	04/09/2004 11:30:00 AM
Last Inspection:	Monday, December 08, 2003

Inspector: Pete Hess, Environmental Scientist III

Weather: Partly cloudy; warm, 50's F

InspectionID Report Number: 240

Accepted by: pgrubaug
 05/07/2004

Permittee: PACIFICORP
 Operator: ENERGY WEST MINING CO
 Site: TRAIL MOUNTAIN MINE
 Address: PO BOX 310, HUNTINGTON UT 84528
 County: EMERY
 Permit Type: PERMANENT COAL PROGRAM
 Permit Status: ACTIVE

Current Acreages

3,539.00	Total Permitted
10.69	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no compliance actions pending for the Trail Mountain permit area. There are two permit conditions included in Attachment "A" of the current State permit, which remains in effect until February 21, 2005. The first permit condition requires that all water monitoring information be submitted in electronic form to the Division's electronic web site. The permittee continues to meet this requirement, submitting the water monitoring data on a quarterly basis. The second permit condition requires that the permittee must monitor intercepted ground water flows which sustain a flow volume of 5 GPM or more from a single source during development mining. Although there are additional requirements to the permit condition, all are meaningless at this time as all extraction activities have ceased and the Mine is sealed. No mining has occurred since May of 2001, when the permittee notified the Division that it was placing the site in temporary cessation status. Today's inspection was conducted in order to examine the site's field conditions relative to the complete inspection conducted during March 2004. At that time, the entire site was under 18-20 inches of snow.

Inspector's Signature: _____

Date: Tuesday, April 20, 2004

Pete Hess, Environmental Scientist III
 Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Permit Number: C0150009
 Inspection Type: PARTIAL
 Inspection Date: Friday, April 09, 2004

Inspection Continuation Sheet

REVIEW OF PERMIT PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

4.a Hydrologic Balance: Diversions

All diversions which were inspected were capable of functioning as designed.

4.d Hydrologic Balance: Water Monitoring

There was a small amount of flow observed in Cottonwood Creek this day.

14. Subsidence Control

All mining activities at the site ended in March of 2001. The permittee continues to submit subsidence monitoring information for the Trail Mountain permit area as part of the 2003 Annual Report. The review of that submitted information is pending.

15. Cessation of Operations

There has not been any change in the temporary cessation status for the Trail Mountain site.

22. Other

The chain link fence barricades which have been secured out by the Mine portal seals appear to be sound and in good repair. Tampering by unauthorized persons was not apparent.