



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

C0150009
Outgoing
#4302
R

June 26, 2013

Ken Fleck
Energy West Mining Company
P.O. Box 310
Huntington, Utah, 84528

Subject: 2012 Annual Report Review Completion, Trail Mountain Mine, C/015/009, Task ID #4302

Dear Mr. Fleck:

The Division staff has completed the review of the 2012 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on June 26, 2013.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
Enclosure
O:\015009.TMT\WG4302\ReviewCompletionLetter.doc



Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	PacifiCorp	Mine Name	Trail Mountain Mine
Permit Number	C/015/0009	Permit expiration Date	2015-02-20
Operator Name	Energy West Mining Co	Phone Number	+1 (435) 687-9821
Mailing Address	PO Box 310	Email	
City	Huntington		
State	Utah	Zip Code	84528

DOGM File Location or Annual Report Location

Excess Spoil Piles	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Not Required	
Refuse Piles	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	
Impoundments	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not Required	
Other:		

OPERATOR COMMENTS

Mine has been in cessation since 2001

REVIEWER COMMENTS

Met Requirements

Did Not meet Requirements

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Mine has been in cessation since 2001

Reviewer Comments

The Permittee submitted subsidence monitoring data for Areas 27 and 28, which are associated with secondary coal extraction at the Deer Creek Mine / Mill Fork lease area. Areas 23 and 24 are associated with the Trail Mountain Mine. As noted elsewhere, mining via longwall methods was completed at Trail Mountain in 2001, and the mine was sealed. The Division is aware that the predicted subsidence associated with longwall mining occurs within six months to one year after the completion of the panel. The 2006 Annual Report concluded in that subsidence monitoring review that Area 24 had reached maximum deformation many years ago and that no future settling will occur. This is confirmed on Page 3 of the 2012 Annual Subsidence Monitoring Report. "Other areas where mining has not occurred for 5 years or more are considered to be completely subsided. They are; ...14-26...(thus areas 23 and 24 is included) covering the old mine areas including Rilda Canyon Ridge". (PHH, 3/26/2013)

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
NA		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements

The mine is in cessation.