

0002

Route #File XMY



*Just
MFW
JSS
D
gel*

Consolidation Coal Company
Western Division
EMERY MINE
P. O. Box 527
Emery, Utah 84522
801-286-2301

November 26, 1979

K. Michael Thompson
Engineering Geologist
State of Utah-Department of Natural Resources
Division of Oil, Gas, and Mining
1588 West North Temple
Salt Lake City, Utah 84116

RE: Emery Deep Mine
Emery County, Utah
ACT/015/015

Dear Mr. Thompson:

In accordance with the directive of the Division, Consol has completed remedial action to correct piping under the intake facility for the sediment pond on the north side of the creek.

Measures taken to correct this problem included excavation of the affected area, recompaction of the backfill, and providing a lining in the channel to convey run-off to the pond intake.

Sincerely,
Ronald Thompson
Ronald G. Thompson
Engineer

cc.
Ms. Eileen Dougherty, OSM
Mr. T. O'Conner

