

0001

STATE OF UTAH
NATURAL RESOURCES & ENERGY
Oil, Gas & Mining

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

December 21, 1981

Dean C. Bray
Consolidation Coal Company
Western Region
Emery Mine
P.O. Box 527
Emery, Utah 48522

RE: Christiansen Wash Repair Work
Emery Mine
ACT/015/015
Emery County, Utah


Dear Mr. Bray:

On September 14, 1981, Consol was given verbal approval to repair damage caused by flooding on September 8, 1981. A follow-up letter dated September 15, 1981, from the Division outlined eight stipulations for the approval for the repair work. Correspondence between then and December 14 (including the plan that was submitted September 25, 1981) has adequately addressed the stipulations.

On December 16, 1981, Sandy Pruitt of the Division made an on site inspection and noted that the reclamation work had not been completed. This work should be done at the first appropriate opportunity. Ideally, this would be late fall or during the winter when the soil is not frozen or covered with snow.

Should any problems or questions arise, please contact Sally Kefer or Lynn Kunzler of my staff.

Sincerely,



JAMES W. SMITH
COORDINATOR
MINED LAND DEVELOPMENT

cc: Office of Surface Mining

JWS/LMK:tr