

0005



Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

File ACT/015/015
Folder No. 2, 7
Copy to Sue,
Rick, Dave D.,
Dave L.
Wayne

December 12, 1983

Mr. James Smith
Division of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, UT 84114


RE: ACT/015/015

Dear Mr. Smith:

Pursuant to rule UMC 817.46 (t) Consolidation Coal Company - Emery Mine, hereby requests that pond and impoundment inspections for structures not designated by 30 CFR 77.216 (a) be performed on a quarterly basis. Please note that none of the existing ponds at the Emery Mine meet the size criteria of 30 CFR 77.216 (a).

Consol plans to begin quarterly inspections of these structures starting January 1984. If you have any questions or comments please contact me.

Sincerely,


Ronald O. Hughes
Mine Engineer

RECEIVED
DEC 14 1983

DIVISION OF
OIL, GAS & MINING