

RECEIVED
OCT 14 1983



File
ACT/015/015
Folder No. 2
Copy to Lynn

Consolidation Coal Company
Western Region
Emery Mine
P. O. Box 527
Emery, Utah 48522

DIVISION OF
OIL, GAS & MINING

JIM

OCT 14 1983

State of Utah
Division of Oil Gas & Mining
4241 State Office Building
Salt Lake City, Utah 84114

ATTN: Jim Smith (six [6] copies)

U.S. Office of Surface Mining
Brooks Towers
1020 15th Street
Denver, CO 80202

ATTN: Betty Thalhofer (eight [8] copies)

Richardson Associates
P.O. Box 5111
Denver, CO 80217

ATTN: Debby Richardson (one [1] copy)

RE: Apparent Completeness Review Response
Emery Deep Mine
ACT/015/015

Dear Mr. Smith:

I am enclosing copies of a plate showing improvements to the water management system for the intermediate catch basin at the Emery Mine. This plate should be placed in the Apparent Completeness Review Response provided to your office by Richard Holbrook of Consol's Denver office. The map should be placed in the map pocket provided behind the tab divider "Diversion Rev." of Volume 13 of the ACR response.

If you have any questions please contact Richard Holbrook at (303) 770-1600.

Sincerely,

for Ron Hughes
Mine Engineer

cc: R. Holbrook w/l copy