

FILE ACT/015/015  
FOLDER # 7

0041



SCOTT M. MATHESON  
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES

CHARLES R. HENDERSON  
Chairman

CLEON B. FEIGHT  
Director

DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

JOHN L. BELL  
C. RAY JUVELIN  
THADIS W. BOX  
MAXILIAN A. FARBMAN  
EDWARD T. BECK  
E. STEELE McINTYRE

Vacation or Termination of Notice or Order

To the Following Permittee or Operator:

Name Consolidation Coal Co.

Mailing Address P.O. Box 527 EMERY, UT 84522

State Permit No. ACT/015/015

Utah Coal Mining and Reclamation Act, Section 40-10-1 et. seq., Utah Code Annotated (1953):

Notice of Violation No. N 83-4-11-2 Y  TV  dated Aug. 31, 19 83.

Cessation Order No. C \_\_\_\_\_ Y  TV  dated \_\_\_\_\_, 19 \_\_\_\_\_.

Violation No. 1 is hereby \_\_\_\_\_ Terminated  X Vacated because:

Violation No. \_\_\_\_\_ is hereby \_\_\_\_\_ Terminated  \_\_\_\_\_ Vacated because:

Violation No. \_\_\_\_\_ is hereby \_\_\_\_\_ Terminated  \_\_\_\_\_ Vacated because:

Date of Service Nov. 1, 1983 \_\_\_\_\_  
Signature of Authorized Representative David Lof

Time of Service or Mailing 10:15 X a.m. \_\_\_\_\_ p.m. \_\_\_\_\_  
Name and I.D. No. DAVID LOF #4

THE CONCERN OF THE VIOLATION WAS THAT SEDIMENT POND #5 WAS NOT DESIGNED TO HANDLE THE ADDITIONAL RUNOFF WHICH WAS SUPPOSED TO BE DIVERTED BY THE UNDISTURBED DIVERSION. FURTHER DISCUSSION WITH THE OPERATOR AND REVIEW OF THE MINE PLAN ~~##~~ SHOWED THAT THE SEDIMENT POND WAS DESIGNED TO ADEQUATELY HANDLE THE ADDITIONAL RUNOFF.