

0013

File: ACT/015/015
#79


5
January 7, 1984

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

Mr. D. Wayne Hedberg
Division of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Dear Mr. Headberg:

During the month of December 1984 I traveled to all the ponds in use at the Emery Mine. These ponds are, #1, 2, 3, 5, and the R/O lagoon. I inspected the ponds for structural integrity and erosion. With the exception of pond #2 all ponds were in sound condition and had very little erosion. Pond #2 is in sound condition, but there is some erosion on the western slope. This erosion does not affect the pond's strength or function, but will be repaired in the near future.

If you have need of futher information, please contact me.

Sincerely,



Ronald O. Hughes
Professional Engineer

RECEIVED

JAN 09 1985

DIVISION OF
OIL, GAS & MINING