

March 20, 1985

TO: Coal File, Inspection and Enforcement
FROM: Barton Kale, Mining Field Specialist *BOK*
RE: Consolidation Coal Company, Emery Deep Mine, ACT/015/015,
Folder #7, Sevier County, Utah

A partial inspection was conducted at the above mentioned mine site by Barton Kale of the Division. The inspector was accompanied by Ron Thompson of Consolidation Coal Company.

Emery Deep mine is now back in production. A quick tour of the site was made to ensure general compliance and to specifically check some potential problem areas mentioned during the previous inspection.

The sediment pond diversion ditch (the sediment pond across the bridge from the main pad) has received grading and is now up to level. If additional undercutting is observed then additional measures will need to be taken (such as using old belting or other linings).

Scrap and waste equipment has been pulled back from the berm at the old scrap area. Employees have been warned to keep scrap controlled. All culverts were operating including the areas in need of maintenance during the last inspection.

The erosion site fixed with drain rock last year is still stable with no additional erosion noted.

re

cc: Donna Griffin, OSM
Ron Thompson, Consol
Sue Linner, DOGM
Joe Helfrich, DOGM

Statistics:

Vehicle: 45429 X 760 miles
Per Diem: 1 person X 2 days, 4 hours = \$90
Grant: A&E

0181Q-10