

0013

RECEIVED  
OCT 06 1986



DIVISION OF  
OIL, GAS & MINING

Consolidation Coal Company  
Emery Mine  
P. O. Box 527  
Emery, Utah 84522  
(801) 286-2301

October 3, 1986

Mr. D. Wayne Hedberg  
Division of Oil, Gas, and Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

Re: Quarterly Pond Inspections  
Emery Deep Mine  
ACT/015/015

Dear Mr. Hedberg,

The following is a summary of the quarterly pond inspections for the second quarter of 1986.

Pond #1 - (main mine sedimentation pond)

Date: 9/30/86

Time: 14:15

Comments: The pond was discharging with a staff gage reading of 0.20. There were no visual signs of erosion, piping, or seepage. The embankment was in sound condition.

Pond #2 - (main mine yard sedimentation pond)

Date: 9/30/86

Time: 14:49

Comments: The pond was dry. There were no visual signs of erosion, piping, or seepage. The embankment was in sound condition. The outlet gate was in good working condition. The outlets and inlets were free of obstructions.

Pond #3 - (secondary mine yard sedimentation pond)

Date: 9/30/86

Time: 15:00

Comments: The pond was dry. There were no visible signs of erosion, piping, or seepage. The embankment was in sound condition. The outlet gates were in good working condition. The inlets and outlets were free of any obstructions.

Pond #5 - (prep. plant sedimentation pond)

Date: 9/30/86

Time: 14:45

Comments: The pond was dry. There were no visual signs of erosion, piping, or seepage. The embankment was in sound condition. The outlets and inlets were free of obstructions.

R/O Lagoon

Date: 9/30/86

Time: 14:30

Comments: There was approximately 2 inches of water standing over approximately one-tenth of the pond. There were no visual signs of erosion, piping, or seepage. The embankment was in sound condition.

*Stephen C. Drummond*

Stephen C. Drummond  
M.S.H.A. Qualified  
Impoundment Inspector