



0009

NO. N87-9-8-3

notice of violation

To the following Permittee or Operator:

Name Consolidation Coal Company

Mine Emery Deep  Surface  Underground  Other

County Emery State Utah Telephone 801/286-2301

Mailing Address P.O. Box 527

State Permit No. ACT/015/015

Ownership Category  State  Federal  Fee  Mixed

Date of inspection Aug 18 & 19, 19 87

Time of inspection 8:00  a.m.  p.m. to 4:00  a.m.  p.m.

Operator Name (other than Permittee) same as above

Mailing Address same as above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., Utah Code Annotated, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is  is not  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Aug 19, 1987 Time of service/ mailing 4:00  a.m.  p.m.

Bon Thompson  
Permittee/Operator representative

Ronald Thompson  
Signature

Mine Engineer  
Title

Holland Shepherd  
Division of Oil, Gas & Mining representative

Holl Shepherd  
Signature

Reclamation Specialist  
Title

#9  
Identification Number

SEE REVERSE SIDE

WHITE-DOGMI YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

923



NOTICE OF VIOLATION NO. N 87-9-7-3

Violation No. 1 of 3

Nature of violation

Failure to collect ground water monitoring data  
in a manner approved the Division.

Provisions of act, regulations or permit violated

UMC 817.52 (a) (1)

Portion of operation to which notice applies

The operator is missing ground water monitoring data  
in 1986 (Sept. monitoring) for wells Bryant and TIBG.  
Also missing is information for Bryant, Lewis and IU2  
in May of 1987

Remedial action required (including any interim steps)

No remedial action is required because of the  
nature of the violation.

Abatement time (including interim steps)

None the violation will be terminated effective  
Aug. 19, 1987.



**NOTICE OF VIOLATION NO. N 87-9-7-3**

Violation No. 2 of 3

Nature of violation

Failure to construct a diversion facility in a manner which would prevent additional erosion to the disturbed area.

Provisions of act, regulations or permit violated

UMC 817.45 (iii) (e)

Portion of operation to which notice applies

Pond # 5 of the operator's preparation plant area (proposed area) has developed severe erosion at the northeast corner. Water has piped around the constructed inlet structure as well as under it.

Remedial action required (including any interim steps)

1) Reconstruct diversion - inlet at point where it enters pond # 5 (NE corner) in a manner which will prevent future erosion.

Abatement time (including interim steps)

1) by Sept 30<sup>th</sup> 5:00 p.m. 1987



NOTICE OF VIOLATION NO. N87-9-7-3

Violation No. 3 of 3

Nature of violation

Failure to manage an underground opening in a manner which would prevent injury to livestock, wildlife or people.

Provisions of act, regulations or permit violated

UMC 817.13

Portion of operation to which notice applies

An 18 inch air vent (vertical shaft) has been left uncovered. The vent is located in the proposed preparation plant area, just southeast of the area's topsoil stockpile.

Remedial action required (including any interim steps)

1) Cover air vent by most practicable means possible

Abatement time (including interim steps)

1) by Sept. 30<sup>th</sup> 5:00 p.m. 1987