



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0014

Jake

Joh

SCL

Norman H. Bangertter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 5-29-87
11:00 to 1:00

Permittee and/or Operators Name: Consolidation Coal Company
Business Address: P.O. Box 527 Emery, Ut 84522
Mine Name: Emery Deep Permit Number: ACT/015/015
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Russell Jensen
State Official(s): Holland Shepherd
Partial: Complete: Date of Last Inspection: 3-19-87
Weather Conditions: rain showers, cloudy, slight runoff
Acreage: Permitted 5180 Disturbed 40 Regraded 2.66 Seeded 2.66 Bonded 247
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION 5-29-87

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits:

The Emery Deep mine has been active again since the first week of May 87. The operator has sent a letter to the Division verifying the reactivation of this site. The operation has been inactive from 1-87 to 5-87. According to Mr. Ron Thompson of Consol, the operation will remain active indefinitely.

6. Development Waste and Spoil:

The operator has moved most of the underground development waste which had been stored in the materials storage ^{YARD} by pond #3 to the west temporary coal stockpile yard situated above and to the southeast of the evaporation lagoon area. The operator has not, as yet, decided on a permanent site for disposal of this material. According to Mr. Jensen the waste material was moved to allow room in the materials storage yard for the storage of more coal. According to Mr. Thompson the stored material contains approximately 15,000 yards of development waste.

13. Revegetation:

1. The operator and I observed the new test plots that were installed April of 87. The plot installation was observed by James Leatherwood and Lynn Kunzler of the Division, during installation.

2. We also looked at the revegetation efforts that were initiated 1 year ago during the installation of the evaporation lagoon. Much of the vegetation on the pond embankments is of a weedy nature (predominantly Halogeton). Some of the planted species are evident, however sparse (mostly Crested Wheatgrass and Sweetclover).

Copy of this Report:

Mailed to: Ron Thompson, Donna Griffin

Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd #9 Date: 6-3-87