



1/2-2-87

0017

file

gch

SC

inspection report

Permit No. AG/015/015

Inspection Date 1-22-87

Permittee/Operator Name Consolidation Coal Company

Business Address P.O. Box 527

City Emery State Utah Zip 84522

Mine Emery Deep  Surface  Underground  Other

County Emery State Utah

Company Official(s) Steven Drummond

State Official(s) Holland Shepherd, Rick Summers

Time of inspection 10:00  a.m.  p.m. to 12:30  a.m.  p.m.  Partial  Complete

Date of last inspection 12-11-85 Weather conditions sunny-cold, snow on ground

Acreage 5180  Permitted 40  Disturbed 2.66  Regraded 2.66  Seeded 247  Bonded

Enforcement Action none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
- Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### INSPECTION REPORT COMMENTS

Permit No. ACT/015/015

Inspection Date 1-22-87

Please number comments to correspond with topics on previous page.

1. Permits:

The operator formally notified DOGM this month indicating that the operation will be inactive starting December 29, 1986 for an indefinite period of time. Mr. Drummond indicated, at the time of this inspection, that the production stoppage would probably continue for an extended period of time.

13. Revegetation:

Mr. Drummond related that work on the areas disturbed last summer, during a small mine fire, would not be started until early this spring. He indicated that finding an acceptable contractor, earlier on, had not worked out. The operator now plans to do the work himself.

4. Sediment Ponds:

1. Material that had been encroaching on the pond associated with the refuse storage yard (pond #3), has been removed by the operator. Much of the material was removed to a sanitary landfill.

2. The mine water pond was discharging at the time of inspection. A full suite of samples was collected.

Copy of report mailed to Steve Drummond, Donna Griffin

Copy of report given to Rick Summers

Inspector's signature Hille Shyba #9 2-2-87 No. \_\_\_\_\_

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE