

0009

015/015



Consolidation Coal Company
Mid-Continent Region
12755 Olive Boulevard
St. Louis, Missouri 63141
(314) 275-2300

RECEIVED
AUG 06 1990

DIVISION OF
OIL, GAS & MINING

August 2, 1990

Mr. Lowell Braxton
Utah Division of Oil, Gas & Mining
355 W. North Temple
3 Triad Center - Suite 350
Salt Lake City, UT 84180-1203

Dear Mr. Braxton:

Enclosed please find various monitoring data for the 2nd quarter of 1990 for the Emery Mine. These include:

- 1) Streamflow and analytical results for the surface water sites, (Samples were tested for baseline parameters);
- 2) Static water-level data and analytical results for well sites, (Samples were tested for baseline parameters);
- 3) Spring flow information.

Water samples could not be collected from Wells SM1-2 and IU2. Well SM1-2 contained only six inches of water and was too shallow to sample. The dedicated pump in Well IU2 could not be started with the present portable generator.

Static water level readings in Wells R2(M), R2(U) and H(M) remain suspect.

If you have any questions concerning this information, please call.

Sincerely,

Richard Denning

/vms

Enclosure