



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1027
jak

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 7/25/91
12:30 pm- 2:30 pm

Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 527 Emery Utah, 84522
Mine Name: Emery Deep Permit Number: Act 015/015
Type of Mining Activity: Underground x Surface Other
County: Emery Company Official(s): Mike Jacobsen
State Officials(s): Sharon Falvey
Federal Official(s): none
Partial: x Complete Date of last Inspection: 06/12/91
Weather Conditions: Calm, Overcast
Acreage: Permitted 5180 Disturbed 40 Regraded 2.7 Seeded 2.7
Bonded 207 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	(x)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(x)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(x)	()	()	(x)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION: 7/25/91

(Comments are Numbered to Correspond with Topics Listed Above)

At first arrival at the site the only available company representative was Karri Lou Gremmel, Office Manager. I began the inspection without a company representative. Mike Jacobsen of Consolidation Coal Co. accompanied me, during the last half hour of the inspection. Prior to leaving the site, some precipitation began to fall. No surface site runoff occurred during my inspection.

1. Permits

An updated surface facilities map was requested by Stephen Demczak during the June 12, 1991 inspection. At this time these maps were not received by the Division. The operator proposes to move the diesel fuel and coal oil tanks from the underground location to the surface. The proposed surface location for the tanks is at sites 14 and 16 on the facilities area map, Plate II-1. A Storage Trailer and Tipple Office Trailer were previously removed from this location. This proposed action should be submitted to the Divisions a formal amendment, addressing R614-301-526.200, and other pertinent R614 regulations as well as any State and Federal regulations that might apply.

8. Noncoal Waste

Noncoal Waste was visible at the base of coal stockpile area number 31. This area according to Plate II-1 is not designated for noncoal waste but, is part of thier disturbed area. The wastes, metal grates and machinery, appeared to be present at the location for a considerable period of time . These items should be removed from this location and placed in a correctly designated area.

Copy of this Report:

Mailed to: Brian Smith (OSM), Dee Brey Emery Deep Mine
Given to: Joe Helfrich and Daron Haddock DOGM

Inspector's Signature & Number: Sham K. Fabry #38 Date: 2/25/91