

0003

D15/015 #2

Consolidation Coal Company
Mid-Continent Region
12755 Olive Boulevard
St. Louis, Missouri 63141
(314) 275-2300

December 15, 1993

Mr. Daron R. Haddock
Utah Div. Oil, Gas & mining
355 W. North Temple
3 Triad Center - Suite 350
Salt Lake City, UT 84180-1203

RECEIVED

DEC 16 1993

DIVISION OF
OIL, GAS & MINING

Re: Emery Mine Permit #ACT 015/015,
Division Order #93B Deficiency Response

Dear Mr. Haddock:

Per the above referenced order, find responses to Requirements 1 through 4. Regarding Requirement #1, the permit has been updated to include changes to Pond #8. Requirements 2 and 3 have reclassified any necessary small area exemptions as alternative sediment control areas with design information provided.

Requirement 4 has been partially met with a sample of a cross-reference to link the MRP with R645 rules. If this reference is satisfactory, please indicate so and we will provide the Department with the remaining sections and appropriate certifications.

If any questions, contact this office.

Sincerely,



John A. Gefferth
Group Leader - Permits

JAG/vms

A:\HADEMDR.93B

Enclosures