

0013



CONSOL ENERGY™

Emery Mine
P.O. Box 527
Emery, Utah 84522
(801) 286-2301

015/015

Incoming

OL

May 3, 2002

Mr. Daron Haddock, Permit Supervisor
Utah Coal Regulatory Program
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

RE: Blasting Permit - Corrected Pages for Chapter IV.A.4, pg. 10

Dear Mr. Haddock:

Please find enclosed five (5) copies of page 10 of Chapter IV – Use of Explosives at the Emery Mine (Permit ACT/015/015). The pages that were originally submitted with the Blasting Plan for 4th East Portal excavation contained a strike through for the deleted words and underlined for changes. These pages have been corrected and do not show the sentences striked through nor underlined.

I have forwarded a copy to the Price Field Office.

If you have any questions or concerns, please feel free to contact me at (435) 286-3512.

Sincerely,

Seth McCourt
Mining Engineer- Emery Mine

CC: Steve Demzcak, DOGM Price Field Office
Tim Kirschbaum, CONSOL

RECEIVED

MAY 05 2002

DIVISION OF
OIL, GAS AND MINING