

0014



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Handwritten notes: 'SLO by JO' and 'OK'

INSPECTION REPORT

Partial XXX Complete \_\_\_ Exploration \_\_\_
Inspection Date: 06/27/2002 Time: 11:00am-3:00pm
Date of Last Inspection: 05/29/2002

Mine Name: Emery Deep Mine County: Emery Permit Number: C/015/015
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 566, Sesser IL 62884/P.O. Box 527, Emery, Utah 84522
Company Official(s): Seth McCourt
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, Sunny, 90's
Type of Mining Activity: Underground XXX Surface \_\_\_ Prep Plant \_\_\_ Other \_\_\_
Existing Acreage: Permitted 5180 Disturbed 247 Regraded \_\_\_ Seeded \_\_\_
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, etc.

**INSPECTION REPORT**  
(Continuation Sheet)

PERMIT NUMBER: C/015/015

DATE OF INSPECTION: 06/27/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

**1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

The permittee has only the Modification to the 4<sup>th</sup> East Portals Facility amendment for review at the Division.

**2. SIGNS AND MARKERS**

The identification sign at the 4<sup>th</sup> east portal is located on the fence entering the facility. All necessary information is on the sign as required by the R645 Coal Rules.

**3. TOPSOIL**

The permittee was 90 percent complete in constructing a berm completely around the topsoil pile.

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

The undisturbed area diversion was completed.

**4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS**

The permittee will construct the sediment ponds after the topsoil berm is completed.

**4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES**

The permittee has added additional silt fence on the lower end of the disturbed area to catch sediment and treat water runoff.

**4D. HYDROLOGIC BALANCE: WATER MONITORING**

The permittee was informed that the Division would not accept "No access" to a water-monitoring site as a way of complying with the requirements of the R645 Coal Rules and the MRP.

**5. EXPLOSIVES**

The permittee has started to use explosives for the development of the 4<sup>th</sup> East Portals. The permittee will be using five pounds or more of explosives. The main gate to the 4<sup>th</sup> East Portals is where the "Explosive in Use" sign is located. Blasting signs are stored on the property and are installed prior to a blast. Road is closed off prior to a blast with contractor personnel.

INSPECTION REPORT  
(Continuation Sheet)

PERMIT NUMBER: C/015/015

DATE OF INSPECTION: 06/27/2002


6. **DISPOSAL OF EXCESS WASTE/FILLS/BENCHES**

Spoil material is being stored and is bermed within the 4<sup>th</sup> East Portal area.

12. **BACKFILLING AND GRADING**

The final grading of the 4<sup>th</sup> East Portal facility is near final grade.

Inspector's Signature: \_\_\_\_\_

  
Stephen J. Demczak #39

Date: July 5, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM  
Tim Kirschbaum, Consol, Illinois  
Steve Behling, Consol, Emery  
Price Field office

O:\015015.EME\Compliance\2002\p\_0627.doc