

**CONSOL ENERGY™**

Consolidation Coal Company

P.O. Box 566

Sesser, IL 62884

Phone: (618) 625-2041

Fax: (618) 625-6844

March 18, 2003

Mr. Daron R. Haddock, Permit Supervisor  
Utah Coal Regulatory Program  
Division of Oil Gas & Mining  
1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801

*Incoring*  
*C/015/015*

Re: Resubmit As-Built Drawing  
4th East Portal, Consolidation Coal Company, Emery Deep Mine  
Permit C/015/015-AM02B

Dear Mr. Haddock:

This letter and enclosed drawing is submitted to modify deficiencies noted with our January 22, 2003 submittal. The enclosed drawing the changes required of the as-built configuration and volumes for the sediment pond, topsoil stockpile and temporary diversion constructed at the 4th East Portal. Please replace/insert the drawing within Volume 2 of 2 of Chapter VI as Plate VI-20a of the MRP.

If you have any questions concerning this certification, please contact me at this office.

Sincerely,

Timothy D. Kirschbaum  
Environmental Engineer  
(618)-625-6847

cc: S. McCourt, Emery Mine

RECEIVED

MAR 21 2003

DIV. OF OIL, GAS &amp; MINING