

From: Priscilla Burton
To: John Gefferth
Date: 1/27/2006 2:25:29 PM
Subject: Emery Maps Tsk 2334

Hello John,
As discussed over the phone yesterday, I have the following deficiencies with the maps:

Plate I-1

Increase font size so names are legible on the map.
Update Appendix 1-3 to correspond with current ownership of coal and surface as shown on map and as per your most recent records. RE: coal ownership parcel 677-017 M. Robertson previously leased to consol, but presently owned by Consol in Sec 31, R6E T22S.

Plate IX - 1

Show all Quaternary deposits in legend (alluvial, colluvial, fan, and pediment deposits)
Show topographic features i.e. Walter Flat
Label Quitcupah Creek and extend boundary of map to Muddy Creek on East and Hydrologic Divide (Joes' Valley Zone) on West
Keep the USGS monitoring points on the map
Show historic flood irrigation in Sec 20, 21, 22 of R6E, T22S, etc. in vicinity of current and projected workings.

Plate [IX] -2

Label the town of Emery
Note the soils of alluvial deposition in the First No. Incidental Boundary Change (similar to those noted adjacent to Quitcupah Creek).

Thank you,
Priscilla.

Priscilla Burton
Environmental Scientist III/Soils
Utah Division of Oil Gas & Mining
Price Field Office
455 West Rail Road Ave.
Price UT 84501

priscillaburton@utah.gov
(435) 613-1146 x 207

CC: Demczak, Steve; Grubaugh-Littig, Pam