

0049

From: "Gefferth, John" <JohnGefferth@consolenergy.com>
To: "Pam Grubaugh-Littig" <pamgrubaughlittig@utah.gov>
Date: 5/10/2007 1:05 PM
Subject: Emery Landowner letters
Attachments: Emery Landowners Notification.total.pdf

CC: "Hardy, Russell" <RussellHardy@consolenergy.com>, "Uhe, Cindy" <CindyUhe...
Pam

Attached find a pdf of surface landowner notification accompanied by the return receipts.

We re-notified all current surface owners that will have future mining under their surface for the life of mine.

*Copying OK
C/015/0015*

John Gefferth

Consol Energy

P.O. Box 566

Sesser, Illinois 62884

618-625-6850 office

618-534-5151 cell

618-625-6844 fax

www.consolenergy.com <<http://www.consolenergy.com>>



CONSOL ENERGY™

Consolidation Coal Company

P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

John Gefferth
Consolidation Coal Company
P. O. Box 566
Sesser, IL 62884

**Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company**

Dear Mr. Gefferth:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Sections 21, 22, 23, 27 and 28

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY.

Consolidation Coal Company

P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4972

Kenneth & Earlene Christiansen
P. O. Box 552
Emery, UT 84522-0552

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Mr. & Mrs. Christiansen:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Section 22

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY™

Consolidation Coal Company
P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

Bret Osburn Carter
P. O. Box 24
Emery, UT 84522-0024

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4927

**Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company**

Dear Mr. Carter:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Sections 20, 21 and 29

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY

Consolidation Coal Company

P.O. Box 566

Sesser, IL 62884

(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4934

Russell H. Odle
P. O. Box 23
Emery, UT 84522-0023

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Mr. Odle:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Sections 28 and 29

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY™

Consolidation Coal Company
P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4965

D U Company
53 West Angelo Avenue
Salt Lake City, UT 84115-3719

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Sirs:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Section 22

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY.

Consolidation Coal Company

P.O. Box 566

Sesser, IL 62884

(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4958

John L. & Vickie Byars
P. O. Box 576
Emery, UT 84522-0576

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Mr. & Mrs. Byars:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Sections 21 and 22

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY™

Consolidation Coal Company
P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4941

Wayne & Delise Staley
P. O. Box 83
Emery, UT 84522-0083

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Mr. & Mrs. Staley:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.

Township 22 South, Range 6 East, SLM, Utah
Sections 21 and 28

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,

John Geffert
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY™

Consolidation Coal Company
P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4989

Morgan C. Robertson
P. O. Box 65
Emery, UT 84522-0065

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Mr. Robertson:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.


Township 22 South, Range 6 East, SLM, Utah
Section 29

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,


John Geffert
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office



CONSOL ENERGY™

Consolidation Coal Company
P.O. Box 566
Sesser, IL 62884
(618) 625-2041

February 16, 2007

Certified Mail
Return Receipt Requested
7003 1680 0000 8654 4996

Jay Humphrey
District Manager
Emery Water Conservancy District
P. O. Box 998
Castle Dale, UT 84513

Re: Subsidence Control – Public Notification
Emery Mine DOGM Permit 015/015 IBC
Consolidation Coal Company

Dear Mr. Humphrey:

Notification is hereby provided, pursuant to R645-301-525.700 of the Utah Coal Mining Regulations pertaining to surface effects of underground coal mining activities, to inform you the Emery Mine, owned by Consolidation Coal Company (CONSOL), will be conducting underground mining activities beneath or adjacent to certain property located in Emery County. Public records indicate your surface property lies within the lands designated. Due to the fact that much of the surface ownership has changed hands during the past several years, CONSOL has chosen to re-notify all of the current landowners. Property you own located within the following sections is within our current and future mine plan.


Township 22 South, Range 6 East, SLM, Utah
Sections 20, 21, 22, 23, 27, 28 and 29

Underground mining activities may occur beneath or adjacent to the above described property beginning immediately and will continue throughout the remainder of the permit term.

Consolidation Coal Company's subsidence mitigation plan is presented in Chapter V, Section B of the company's permit (ACT/015/015). The permit is filed with the State of Utah, Division of Oil, Gas and Mining in their Price Field Office, where a copy of the subsidence plan is available for review. The address and telephone number of the office is; 455 West Railroad Avenue, Price, Utah 84501, phone (435)613-1146.

Should you have any questions concerning the above matter, please contact Russell Hardy, Mine Engineer at the Emery Mine (435)286-3513, or myself at (618)625-6850.

Sincerely,


John Gefferth
Environmental Engineer

cc: Karl Houskeeper, DOGM Price Field Office

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Morgan C. Robertson
P. O. Box 65
Emery, UT 84522-0065

COMPLETE THIS SECTION ON DELIVERY

A. Signature Agent
 Addressee

B. Received by (Printed Name) C. Date of Delivery
 Morgan Robertson 2/1/07

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type-
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number

(Transfer from service label)

7003 1680 0000 8654 4989

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Russell H. Odle
P.O. Box 23
Emery, UT 84522-0023

COMPLETE THIS SECTION ON DELIVERY

A. Signature Agent
 Addressee

B. Received by (Printed Name) C. Date of Delivery
 Russell A Odle 2/20/07

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type-
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number

(Transfer from service label)

7003 1680 0000 8654 4934

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Brest Osburn Carter
P.O. Box 24
Emery, UT 84522-0024

2. Article Number

(Transfer from service label)

7003 1680 0000 8654 4927

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X *Brest Carter*

- Agent
 Addressee

B. Received by (Printed Name)

Lori Carter

C. Date of Delivery

2-20-07

D. Is delivery address different from item 1? Yes

If YES, enter delivery address below: No

3. Service Type-

- Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Jay Humphrey
District Manager
Emery Water Conservancy District
P.O. Box 998
Emery, UT 84513

2. Article Number

(Transfer from service label)

7003 1680 0000 8654 4996

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X *Siane S. Bott*

- Agent
 Addressee

B. Received by (Printed Name)

Siane S. Bott

C. Date of Delivery

2/20/07

D. Is delivery address different from item 1? Yes

If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Kenneth & Earlene Christiansen
P.O. Box 552
Emery, UT 84522-0552

2. Article Number

(Transfer from service label)

7003 1680 0000 8654 4972

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X *Ken Christensen*

- Agent
 Addressee

B. Received by (Printed Name)

Ken Christensen

C. Date of Delivery

2-20-07

D. Is delivery address different from item 1? Yes

If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

D U Company
53 West Angelo Avenue
Salt Lake City, UT 84115-3719

2. Article Number
(Transfer from service label)

7003 1680 0000 8654 4969

PS Form 3811, February 2004

Domestic Return Receipt


102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 X *Amanda Williams* Agent Addressee

B. Received by (Printed Name) *Amanda Williams* C. Date of Delivery *2-20-07*

D. Is delivery address different from item 1? Yes No
 If YES, enter delivery address below:



3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

John L. & Vickie Byars
P. O. Box 576
Emery, UT 84522-0576

2. Article Number
(Transfer from service label)

7003 1680 0000 8654 4958

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 X *Ashley McKenra* Agent Addressee

B. Received by (Printed Name) *Ashley McKenra* C. Date of Delivery *2-20-07*

D. Is delivery address different from item 1? Yes No
 If YES, enter delivery address below:

P.O. Box 576

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Wayne & Delise Staley
P.O. Box 83
Emery, UT 84522-0083

2. Article Number
(Transfer from service label)

7003 1680 0000 8654 4941

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 X *Wayne E. Staley* Agent Addressee

B. Received by (Printed Name) *WAYNE E. STALEY* C. Date of Delivery *2-20-07*

D. Is delivery address different from item 1? Yes No
 If YES, enter delivery address below:

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes