

0066


From: "Hardy, Russell" <RussellHardy@consolenergy.com>
To: <pamgrubaughlittig@utah.gov>
Date: 7/18/2007 3:39 PM
Subject: Emery Subsidence Report
Attachments: Emery Subsidence 7-18-07.pdf


CC: <karlhouskeeper@utah.gov>, <waynewestern@utah.gov>, <SteveChristensen@ut...
Please find attached the subsidence report for June.

Russell Hardy
CONSOL ENERGY
Phone: (435) 286-3513
Fax: (435) 286-3516
email: russellhardy@consolenergy.com


Consolidation Coal Emery Mine Subsidence Report for June 2007

- 6-18-07 Brett Carter had said that his field was subsiding. Spread out over field to check for cracks, but didn't find anything. We also monitored the springs.
- 6-29-07 Bret Carter called and Bret, Peter, and Russell looked at the cracks in his field (he cut his hay and the cracks were noticeable) and his fence that was stretching and sagging. Took pictures of both. Also we GPS'd new cracks. PB, RH
















- 7-6-07 Noticed more little cracks on the hill to the north of the main road across the field of Panel 14th West PB
- 7-9-07 No real noticeable cracks over Panel 14th West. Walk it with Greg Hasenfus, Doug White, Randy Stockdale, Russell Hardy, Buck Parrish, Matt Hyita, and Peter Behling. Did some GPS work as well.



7-16-07

Walked over Panel 14th West found more little cracks over the mined area. Some of the cracks seem to be getting bigger.

