

0005

^{OK}
Internal
C/015/0015

From: Priscilla Burton
To: Steve Christensen
Date: Thursday, January 10, 2008 12:20 PM
Subject: Task 2894 Emery 4th East Facilities Storage Area and Fence

CC: Grubaugh-Littig, Pam; Karl Houskeeper

Hello Steve,

This memo completes my review of Task 2894 and should be sent to the PIC room C/015/0015 2008 Internal file. I recommend approval.

The berm along the east fence line is composed of topsoil. The north half of this berm was removed during the construction of the haul loop (Chap IV, p. 7 last para.). It appears from Plate II-3 included with the application, that construction of a new fence to secure the storage yard will not require removal of or affect the remaining topsoil berm.

All berms composed of topsoil will be clearly marked as topsoil storage area (Chap IV p. 7a).

Thanks,
Priscilla.

Priscilla Burton, CPSSc
Division of Oil Gas & Mining
317 Carbonville Rd.
Price UT 84501

priscillaburton@utah.gov
(435) 613-3733