



CONSOL ENERGY™

**COPY**

C/015/0015 Incoming  
cc: Steve C.  
Consolidation Coal Company  
# 3586  
R  
P.O. Box 566  
Sesser, IL 62884  
(618) 625-2041

July 08, 2010

Daron Haddock  
Utah Division of Oil, Gas and Mining  
Coal Program  
1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801

Re: Emery Deep Mine Permit C/015/015  
4 th East pond 9 culvert Citation #10056

Dear Mr. Haddock:

Per the Divisions citation #10056, dated 06/15/2010, please consider this an insignificant revision to correct the plate in question.

Although there are no DOGM regulations requiring that all culverts be labeled, Consol is submitting this Plate with the culvert to pond 9 labeled on the map.

Enclosed please find four (4) copies for your review and executed C1 and C2 forms. A cd with the submittal in pfd format is enclosed.

If you have any questions concerning this request, please contact me at (618) 625-6850.

Sincerely,

  
John Gefferth  
Environmental Engineer

JAG/jag emNOV10056.abate.doc

File in:

- Confidential
- Shelf
- Expandable

Date Folder 070610C/0150015

See: Incoming for additional information

**RECEIVED**  
JUL 06 2010  
DIV. OF OIL, GAS & MINING



