

Incoming
L0150015
OK

OPINION

Consol attempted to mine coal at the head of Miller's canyon.

Due to poor mining practices or misjudgement they took enough coal out from under the normal underground roof that maintained the normal flow of underground water. Thus diverting the natural flow of ground water into the coal mine workings and causing a change in the normal flow of ground water that had been going on since the beginning of time.

This caused a change in the water table and a void in normal underground water routes and causing surface water to cause holes and subsidence to occur under our property.

We would like Consol to try to reach a compromise with us on this problem.



Jon H. Sundstrom
November 27, 2012