

2/015/015 Incoming

Bronco Utah Operations LLC
P.O. Box 527
Emery Utah, 84522
(435) 286-2447

No task required. SRS

April 14, 2016

Steve Christensen
Utah Division of Oil, Gas and Mining
Coal Program
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

RECEIVED
APR 18 2016
DIV. OF OIL, GAS & MINING

Re: Bronco Utah Operations, LLC.
Emery Mine
DOG M Permit No. C/015/015
Ponds 3 and 9 New Drawings

Dear Mr. Christensen:

It was determined by survey, that ponds 3 and 9 had reached clean-out levels, and the sediment in the ponds was subsequently removed to bring them back in to compliance.

Enclosed, please find 2 new drawings of the ponds, compiled from the survey after cleaning and PE certified as required. Additionally, forms C1 & C2 are also included.


As requested per your earlier email, the drawings have been enlarged so the elevations are legible.

Additionally, these drawings are being submitted as as-builts to be added to their respective locations:

Chapter VI, Volume 3 of 3, Pond #3 Plate VI-25 and Pond #9 Plate VI-20.

Please feel free to contact me with any comments or questions.

Sincerely,




Kit Pappas
Environmental Manager

Office - 435-286-2027
Cell - 435-650-7339

jpappas@broncoutah.com
kit@emerytelcom.net

Attachments:



Pond #3

UPPER SPILLWAY - 5914.27
 LOWER SPILLWAY - 5910.74

GUARD RAIL

CHANNEL TRACED FROM AERIAL PHOTO

BEGIN LARGE BOULDERS

| | | | |
|-----------------------------|-----------|---------------------------|--------------|
| CLEANED POND SURVEYS | | BRONCO UTAH OPERATIONS | |
| DRAWN | DATE | DATE | PROJECT NO. |
| WARE SURVEYING | 3/23/2016 | 1408 5893.77 FL CHK | Pond Cleanup |
| APPROVED | | SHEET | |
| SCALE | | 1 | |
| NTS | | | |

RECEIVED
 APR 18 2016
 DIV. OF OIL, GAS & MINING



