

Bronco Utah Operations LLC

PO Box 527

Emery, Utah 84522

435-286-2027

September 12, 2019

VIA E-MAIL

Mr. Steve Christensen
Utah Division of Oil, Gas and Mining
Coal Program
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, UT 84114-5801

**RE: Bronco Utah Operations LLC
Emery Mine
DOGM Permit No. C/015/0015 2018 Annual Report Review Completion Task
5933**

Mr. Christensen:


Per conversations with John Gefferth (Barr Engineering) and subsequent email dated 9/11/19 regarding clarification of waste rock and boxcut material, I offer the following:

The volumes depicted in the annual refuse pile inspection were Emery 2 expansion actual and estimates at the time prior and during construction and have been carried over from the initial 2017 reports.

These volumes will be adjusted in future refuse pile inspection reports to reflect current volumes per the as-built midterm deficiency responses (task ID 5966) under DOGM review.

If you have any questions concerning this request, please contact Kit Pappas at 435-286-2027.

Sincerely,

A handwritten signature in black ink, appearing to read "Kit Pappas", is written over a light gray rectangular background.

Kit Pappas
Environmental Manager