

Document Information Form

Mine Number: C/015/017

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: JULY 17, 1980

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in: C/015, 017, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

July 17, 1980

file

Inspection Memo
to Coal File:

RE: Emery Mining Corp.
Church Mines
ACT/015/017
Emery County, Utah

The above mentioned mine site was visited by Mary Kay Stein, Joe Helfrich and D. Wayne Hedberg from the Division of Oil, Gas and Mining along with Larry Damrau, OSM Inspector, Denver, on July 10, 1980. They were accompanied by Dick Jones and Larry Guymon, Emery Mining Corp.

The following violations were issued:

State Violation #1 MC 717.17(j) Failure to construct and maintain access and haul roads so as to prevent additional contributions of suspended solids to the stream flow.

Portion of the operation to which notice applies:
Berms of access/haul road on permit area to loadout pad.

Violation #2 MC 717.17(a) Failure to pass all surface drainage from the disturbed area through a sedimentation pond or a series of sedimentation ponds prior to leaving the permit area.

Portion of the operation to which notice applies: Pumphouse area including access road and pad adjacent to pumphouse.

Violation #3 MC 717.11(a) Failure to address surface facilities associated with mining operations in mining and reclamation plan, I.E. Mining without a permit.

Portion of the operation to which notice applies: The pumphouse area including access road and pad adjacent to pumphouse.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0004 Date _____

In C/015, 017, Internal

For additional information

Abatement Measures:

Violation #1: Repair and maintain berm along access/haul road.
Abatement time: 2 weeks; July 24, 1980

Violation #2: Construct and maintain sediment control structures so as to prevent additional contributions of suspended solids to the stream flow and to prevent runoff outside the permit area.

Violation #3: Submit plans as required by the Regulatory, include the following information:

- (1) Map of permit area - showing surface facilities and surface disturbance.
- (2) Size of area not included in permit area.
- (3) Runoff and sediment control plans for above mentioned area. I.E. brief description of sediment control facilities; catch basins, culverts, strawdikes, etc.
- (4) Final Reclamation - describe regrading and revegetation plans.

No Federal violations were issued.

Mary Kay Stein *MKS*
Reclamation Officer

MKS/lml

CC: Murray Smith; OSM Denver

For statistics, see Trail Mountain memo dated July 14, 1980