





STATE OF UTAH

Notice of Violation No. N 81-6-1-2

Violation No. 1 of 2

Nature of the Violation

FAILURE TO MAINTAIN SEDIMENT CONTROL MEASURES SO AS TO MINIMIZE EROSION TO THE EXTENT POSSIBLE

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817.45 (iii)  
40-10-18 (i) UTAH CODE ANNOTATED 1953

Portion of the Operation to which Notice Applies

- (1) AREA OF GULLY FORMATION WHERE RUNOFF EXITS DESSERT PAD
- (2) AREA NEAR LOWER MATERIALS STORAGE PAD WHERE PORTION OF PAD USED TO CHANNEL RUN-OFF INTO DITCH HAS ERODED.

Remedial Action Required (including interim steps, if any)

STABILIZE ERODED STRUCTURES AND HENCE FORTH MAINTAIN THESE STRUCTURES SO AS TO MINIMIZE EROSION

Time for Abatement (including time for interim steps, if any)

30 days. Not later than October 4, 1981



STATE OF UTAH

Notice of Violation No. N. 81-6-1-2

Violation No. 2 of 2

Nature of the Violation

FAILURE TO HAVE RECORDS OF BLASTING OPERATIONS AVAILABLE FOR INSPECTION BY DIVISION AND THE PUBLIC ON REQUEST.

Provision(s) of the Regulations, Act, or Permit Violated

UMC 817.68 (a) (b) (c) (d) (e) (f) (g) (h) (i) (j) (k) et al  
40-10-19 (2)(b) Utah Code Annotated 1953  
40-10-17 (2)(c) Utah Code Annotated 1953

Portion of the Operation to which Notice Applies

entire OPERATION

Remedial Action Required (including interim steps, if any)

HAVE AVAILABLE AT MINE OFFICE ALL APPLICABLE BLASTING RECORDS

Time for Abatement (including time for interim steps, if any)

2 WEEKS from Today SEPT 18, 1981.