



0031  
STATE OF UTAH  
NATURAL RESOURCES & ENERGY  
Oil, Gas & Mining

Scott M. Matheson, Governor  
Temple A. Reynolds, Executive Director  
Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

March 15, 1983

Mr. Larry J. Guymon  
Manager of Construction Engineering  
Emery Mining Corporation  
P. O. Box 310  
Huntington, Utah 84528

RE: Slope Failure (2/15/83)  
Des-Bee-Dove Mine  
ACT/015/017  
Folder No. 3 and 13  
Emery County, Utah

Dear Mr. Guymon:

The Division acknowledges receipt of the letter dated February 25, 1983 that notified the Division of a slope failure. There should be more information, however, provided to the Division regarding this matter. These include:

1. Details of the slope failure.
  - A. Area involved? Damages?
  - B. Amount of material moved?
  - C. Type of material that failed?
2. What caused the slope failure?
  - A. Saturation?
  - B. Undercut material?
  - C. Other causes?


Mr. Larry J. Gynon  
ACT/015/017  
March 15, 1983  
Page 2

3. What exactly was done to repair the damage?
  - A. Immediate action to protect safety of workers?
  - B. Details of stabilization efforts.
4. How will the operator prevent future problems with the slope?
  - A. Details of measures to be taken.

Due to the very steep slope and the nature of the surface facilities in the immediate vicinity, the detailed reply to this letter should be received within thirty (30) days.

Your cooperation and timely reply to this matter is appreciated.

Sincerely,



PAMELA GRUBAUGH-LITTIG  
RECLAMATION ENGINEER

PGL/btb

cc: J. Smith, DOGM  
M. Boucek, DOGM  
D. Lof, DOGM