

March 15, 1984

Inspection Memo  
to Coal File:

RE: Utah Power & Light Company  
Des-Bee-Dove Mine  
ACT/015/017, Folder #7  
Emery County, Utah

A partial inspection of the Des-Bee-Dove Mine was conducted on February 16, 1984 by Ken Wyatt, Field Specialist for the Division. Larry Guymon of Emery Mining Corporation accompanied this inspector.

The sediment pond cleaning project has been completed. The spillway was clear of rock and debris. The standpipe decant structure has been replaced and the horizontal culvert patched.

The sediment storage area above the sediment pond was examined. The surface of the sediment was still wet. Mr Guymon indicated that a rock drain and a spillway had been installed at the toe of this sediment storage area to help drain water away from this area.

Fires in the Beehive mine are still ongoing. At this time no progress has been made as far as reopening this mine. The Beehive pad was accessible, drainage in this area is hampered by the muddy conditions of the pad. No compliance problems were observed.

Ken Wyatt *Kw*  
Field Specialist

KW:re

cc: Tom Ehmett, OSM  
Larry Guymon, Emery Mining Corporation  
Joe Helfrich, DOGM  
Mary Boucek, DOGM

Statistics: See UP&L Deer Creek Mine memo dated March 15, 1984  
78960