



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

December 1, 1989

TO: Rick Smith, Permit Supervisor

FROM: Bill Malencik, Reclamation Specialist *WAM*

RE: Inconsistencies - Cottonwood/Wilberg, ACT/015/019
Des Bee Dove, ACT/015/0247

While on a formal inspection and/or routine record review some matters briefly described below appear to be inconsistent when observing conditions on the ground and the official records. These apparent inconsistencies for each of the mines are listed below.

Cottonwood/Wilberg, ACT/015/019

(1) The 7/6/89 permit renewal changed the drainage now designated UD-5 from a disturbed to an undisturbed drainage. Three portals dated 1986 lie within the undisturbed area as designated on the map and such portal areas, in my opinion, lie within the disturbed area. The current position on the portals, in my opinion, cannot be defended.

(2) The leach field being disturbed, boundaries of which are subject to interpretation need additional attention in terms of markers, SAE consideration and sediment control.

Des Bee Dove, ACT/015/0247

(1) Surface facilities map needs to be updated. For example the powder magazine and rock dust bin have been removed from the property. These are still shown on the map. The permit will expire in August. Undoubtedly the operator will commence the renewal process, perhaps in February.

(2) The text in ^{PAP}MRP on the East Mountain Road both in the operation and reclamation sections is in need of clarification. The clarification is needed to avoid problems as it may relate to compliance and class 3 road performance standards.

need more specifics

BJM/lap
cc: UP&L - Guy Davis