



Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

November 8, 1989

TO: Richard V. Smith, Permit Supervisor
FROM: Tom Munson, Reclamation Hydrologist *RVS for*
RE: **Storm Water Impoundment, Utah Power and Light Company,
Des-Bee-Dove Mine, ACT/015/017, Folder #2, Emery County,
Utah**

Synopsis

In a deficiency memo from Bill Malencik to Rick Smith dated October 26, 1989, a deficiency regarding the sediment pond designs contained in the PAP was identified.

Analysis

This deficiency was confirmed after examining Appendix VIII, Storm Water Impoundment Map.

Recommendation

An "as constructed" certified drawing needs to be supplied to the division showing exact configuration of the pond and all inlets and outlets for insertion in the PAP.

djh
AT46/25