

0005



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

October 26, 1989

TO: Richard V. Smith, Permit Supervisor

FROM: Bill Malencik, Reclamation Specialist *BM*

RE: Deficiencies - UP&L, Des Bee Dove Mine, ACT/015/017

SYNOPSIS

During a recent complete inspection, several permit deficiencies were noted. These were briefly mentioned in the inspection report as suggested followup items to be corrected by the operator. These included as built and certified drawings on the sediment pond and the haul road. Also, the insurance certificate needs to be clarified.

PROPOSAL

1. The sediment pond drawing shows two inlets, whereas only one inlet exists on the ground. The discharge from the half round culvert is diverted via a ditch to a natural inlet. The as constructed drawing needs to be updated and certified.

2. The haul road drawings contain a statement "As Constructed, Creamer & Noble." The document does not contain an engineers' stamp nor a certification. In the inspection report, this item was discussed and accepted since it appears that past inspections, including oversights, did not raise this as an issue.

3. The insurance certificate issued by Associated Electric and Gas Insurance Service Limited, policy No. XL0296A88, dated 1/9/89 to 12/24/89 does not list thereon the name of the Des Bee Dove Mine nor the permit number. The policy is issued in the name of UP&L Mining and some documents list the name and permit number of other UP&L mines, but not Des Bee Dove. It would appear that all three mines and permit numbers should be shown on the insurance documents.

This information is submitted for your consideration and whatever action you deem appropriate.

BJM/lap
cc: PFO