

1-17-89  
7060



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*John* *John*

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: January 5, 1989  
9:00 a.m. to 12:00 noon

Permittee and/or Operators Name: Utah Power and Light Company  
Business Address: P. O. Box 310, Huntington, Utah 84528  
Mine Name: Des-Bee-Dove Mine Permit Number: ACT/015/017  
Type of Mining Activity: Underground  Surface  Other   
County: Emery  
Company Official (s): Initially, Val Payne during record review; none for field inspection  
State Official(s): Henry Sauer and Bill Warmack  
Partial:  Complete:  Date of Last Inspection: October 5, 1988  
Weather Conditions: Cold and foggy  
Acreage: Permitted 2847 Disturbed 74.5 Regraded  Seeded  Bonded 74.5  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

PERMIT NUMBER: ACT/015/017

DATE OF INSPECTION January 5, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS
2. SIGNS AND MARKERS
3. TOPSOIL
4. HYDROLOGIC BALANCE
  - a. STREAM CHANNEL DIVERSIONS
  - b. DIVERSIONS
  - c. SEDIMENT PONDS AND IMPOUNDMENTS
  - d. OTHER SEDIMENT CONTROL MEASURES
  - e. SURFACE AND GROUNDWATER MONITORING
  - f. EFFLUENT LIMITATIONS
5. EXPLOSIVES
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL
- d. COAL PROCESSING WASTE
8. NONCOAL WASTE
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES
10. SLIDES AND OTHER DAMAGE
11. CONTEMPORANEOUS RECLAMATION
12. BACKFILLING AND GRADING
13. REVEGETATION
14. SUBSIDENCE CONTROL
15. CESSATION OF OPERATIONS
16. ROADS
  - a. CONSTRUCTION
  - b. DRAINAGE CONTROLS
  - c. SURFACING
  - d. MAINTENANCE
17. OTHER TRANSPORTATION FACILITIES
18. SUPPORT FACILITIES UTILITY INSTALLATIONS

: Copy of this Report:

Mailed to: John Kathman - OSM David Smaldone, UP&L

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: #32 Henry Lauer Date: Jan. 5, 1989

1/13/89

INSPECTION REPORT  
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/017

DATE OF INSPECTION January 5, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Val Payne of UP&L granted Bill Warmack (DOGM) and the undersigned inspector permission to review pertinent records while Mr. Payne was absent. Mr. Payne could not stay because he was required to attend another previously planned engagement.

Dense fog and 1.5 feet of snow rendered field inspection of the mine site impractical. Complete field inspection was not accomplished.

1. Permits - Third and fourth quarter pond inspections were reviewed and found in good order. Water levels were noted; Third Quarter = 6759.57 feet and Fourth Quarter = 6759.47 feet.

Third and Fourth Quarter waste rock disposal site inspections were reviewed. Third quarter were present and found in good order. Fourth quarter inspections were completed, however, results have not yet been compiled by the engineers.

UPDES monitoring indicate no discharge from the Des-Bee-Dove pond during the third quarter. Fourth quarter monitoring is not required, according to the approved permit.

The East Mountain springs water monitoring was present and complete. Fourth quarter monitoring is not required.

Blasting reports were reviewed and no blasting occurred during 1988.

Special Use Permits were noted for the following:

- a. Right of Way grant for captioned storage site (U-53809) granted by the BLM 8/3/84.
- b. Right-of-Way grant for access road between the Wilberg/Cottonwood Mine and Des-Bee-Dove Mine (3137) granted by the Division of State Lands and Forestry, April 2, 1986.
- c. Right-of-Way for access road to the Des-Bee-Dove sediment pond (U-57134) granted by the BLM, April, 1986.

djh  
AT43/12-14