



inspection report

Permit No. ACT/015/017

Inspection Date January 23, 1991

Permittee/Operator Name Pacificorp Electric Operations (PEQ)
 Business Address 324 South State Street P.O. Box 26128
 City Salt Lake City State Utah Zip 84528
 Mine Des-Bee-Dove Mine Surface Underground Other
 County Emery State Utah
 Company Official(s) Guy Davis
 State Official(s) Jess Kelley
 Time of inspection 8:30 a.m. p.m. to 12:30 a.m. p.m. Partial Complete
 Date of last inspection December 18, 1990 Weather conditions Sunny and cold
 Acreage 2847 Permitted 74.5 Disturbed Regraded Seeded 74.5 Bonded
 Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
e Surface and groundwater monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	a Construction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f Effluent limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	b Drainage controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	c Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
6. Development waste and spoil disposal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	d Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date January 23, 1991

Please number comments to correspond with topics on previous page.

1. PERMITS

-Permit Number ACT/015/017 expired August 14, 1990. Since the permit was not renewed in a timely manner, the Division issued a Cessation Order (C.O. #C90-20-2-1) which included a schedule for upgrading the information in the Mine Permit. The permit is presently in the process of upgrading.

-UPDES permit was issued February 11, 1988. UPDES permit number is UT-0023591.

-Liability Insurance is held with Associated Electric and Gas Insurance Services, LTD. Policy Number is X0296A189. Insurance term is from 12-24-89 to cancellation.

-Reclamation bond is a surety bond in the amount of \$1,837,712. Bond is held with American Casualty Company of Reading, Pennsylvania. Bond number is #926-00-83. Bond was issued 1-25-85.

4. HYDROLOGIC BALANCE

(a) Stream Channel Diversions-The large half-round CMP culvert below the lower pad is clear and in good repair.

(c) Sediment Ponds and Impoundments-The sediment pond is almost completely empty except for a small crust of ice. The pond is in good repair. The pond embankments are clean and have very little erosion damage.


10. SLIDES AND OTHER DAMAGE

The large slide below the portal area is partially blocking the main road.

Copy of report mailed to Guy Davis/Pacificorp; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office

Inspector's signature



No. 34

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date January 23, 1991

Please number comments to correspond with topics on previous page.

10. SLIDES AND OTHER DAMAGE (continued)

However, the road is easily passable to small vehicle traffic and drainage has been established and maintained around the slide area.

16. ROADS

(b) All road drainage controls are in good condition. Ditches are clean and dry and all culvert inlets and outlets are clean and free of ice and debris.

(c) Surfacing-Road surfaces are in good condition. Gullying in the portion of the road above the slide area has been repaired (see last inspection report).

The road adjacent to the sediment pond is clean and dry.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS

All support facilities are, of course, idle. Parking areas and access areas are clear and in good condition. All surface facilities are being maintained well in their idle state.

Copy of report mailed to Guy Davis/Pacificorp; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office

Inspector's signature

Gene W. Kelley

No. 34

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE