

0016


UTAH POWER & LIGHT COMPANY

1407 WEST NORTH TEMPLE STREET

P. O. BOX 899

SALT LAKE CITY, UTAH 84110

*Row 1
File in
Deer Creek
copy
M. Shultz
ACT 1005/017
JWG*



Dee

June 12, 1979

Mr. Gary L. Fritz
 U. S. Department of the Interior
 Office of Surface Mining
 Reclamation and Enforcement
 Post Office Bldg. Room #270
 1823 Stout Street
 Denver, CO 80202


Dear Mr. Fritz:

Attached to this letter is a copy of a letter from Mr. Larry Guymon. The letter from Mr. Guymon states that the items listed in Violation #79-V-5-9 No. 1 have been corrected as of June 7, 1979. Specifically, the culvert was corrected such that the water from the affected area is directed to the sediment pond.

The Violation #79-V-5-10 No. 2 issued for our Deer Creek Mine for failure to post adequate signs has been corrected as of June 11, 1979. Violation No. 1 for Deer Creek is being considered, and a response will be forthcoming in the near future.

In the event that this communication raises questions, please call me at (801)350-3003.

Sincerely,




Karl D. Gurr
 Senior Mining Engineer
 Mining and Exploration

KDG:lw:1723

- cc: M. Heward
- R. Jerman
- D. Dewey
- C. Shingleton
- M. Thompson
- L. Guymon
- R. Christensen

attachment




Emery Mining Corporation

— A SAVAGE BROTHERS' COMPANY —

31 North Main St., P.O. Box 310, Huntington, Utah 84528

June 7, 1979



JUN 11 1979

MINING AND
EXPLORATION

Mr. Karl Gurr
Mining and Exploration
UTAH POWER & LIGHT COMPANY
P. O. Box 899
Salt Lake City, Utah 84110

Dear Karl:

The erosion control device off the end of the culvert, draining the Deseret Tipple Yard, is complete as required by the O.S.M.

Sincerely,

Larry J. Guymon
Project Engineer

LJG/lju

cc. File

