

February 19, 1980

Inspection Memo
to Coal File:

RE: Deer Creek Mine
ACT/015/018A
Emery County, Utah

The above mentioned operation was given a follow up inspection on February 5, 1980 by Mike Thompson and Joe Helfrich from the Division.


The purpose of the trip was to inspect the following violation issued by the Office of Surface Mining dated January 10, 1980.

Failure to maintain conveyor facilities to prevent additional contributions of suspended solids to stream flow. No work has been performed to abate the violation. In addition inspectors noticed that the two large culverts under the access road to the stockpile were partially filled with raw coal. This resulted from road maintenance in the stockpile area. The following violation was issued:

MC 715.17(c)(1) Failure to maintain culverts as to prevent additional contributions of suspended solids to streamflow.

No other violations were issued.

JOSEPH C. HELFRICH
RECLAMATION OFFICER



JCH/te

cc: Murray Smith, O.S.M.

Note: for statistics see Co-op Mine memo dated February 19, 1980.