

0002

November 4, 1982

Inspection Memo  
to Coal File


RE: Utah Power and Light Company  
Deer Creek Mine  
ACT/015/018-A  
Emery County, Utah

On July 20, 1982, a partial inspection was conducted at the above mentioned minesite by Division Inspector David Lof. He was accompanied on the inspection by Val Payne of Emery Mining Corporation.

Realignment of the ROM conveyor was not completed during the mine vacation. However, Mr. Payne informed me that Emery Mining Corporation was still planning on doing the realignment work this year.

Some of the disturbed area runoff diversion system inlets on the shop/warehouse/parking lot pad still needed to be cleaned out. The operator was given one week in order to have this work completed.

A significant amount of erosion was occurring on the downslope from the south side of the water tank/fuel tank pad. The operator was asked to establish a controlled drainage path off of the pad by either rip-rapping the existing path or conveying the runoff down the slope via a culvert or some other applicable means.



DAVID LOF  
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM  
Val Payne, Emery Mining Corporation

Statistic:

Vehicle: EX #45421 -- 547 miles  
Per diem: one person X two days, 10 hrs. = \$95.56  
Grant: A & E