

June 2, 1983

Inspection Memo
to Coal File:

RE: Utah Power & Light Company
Deer Creek Mine
ACT/015/018-A
Folder No. 7
Emery County, Utah

A partial inspection of the above mentioned minesite was conducted on May 11, 1983 by Ken Wyatt of the Division. Val Payne and Bob Willey accompanied this inspector. The weather was cloudy and cold with intermittent snow showers.

Sedimentation control plans for the conveyor system were resubmitted on May 31, 1983 following an on-site meeting held between UP&L, Emery Mining Corporation and the Division technical staff involved on this review. These new plans reflect more efficient solutions agreed upon during this meeting. Approval of these plans is pending at this time and should be forthcoming in the near future.

At the time of this inspection the waste rock disposal situation as described in NOV N83-4-4-1 is still unsettled. Rock material was still being applied to the northeastern end of the material's storage pad. The adequacy of this area as a waste rock disposal site is pending approval of the permanent program MRP submittal.

The undisturbed diversion drainages were flowing unobstructed into the bypass culvert system at the time of this inspection. No compliance problems were observed.

KEN WYATT *KW*
FIELD SPECIALIST

KW/lm

cc: Tom Ehmett, OSM
Larry Guymon, Emery Mining Corp.
Joe Helfrich, DOGM
Mary Boucek, DOGM

Statistics:

See Valley Camp of Utah, Belina #1 Mine memo dated May 31, 1983.
Grant: A & E