

0040

UTAH POWER & LIGHT COMPANY

1407 WEST NORTH TEMPLE STREET

P. O. BOX 899

SALT LAKE CITY, UTAH 84110

FILE

ACT/015/018, #2

cc Hamm

RECEIVED

February 8, 1985

FEB 11 1985

DIVISION OF OIL
GAS & MINING

Mr. Louis Hamm
U. S. Department of the Interior
Office of Surface Mining
Reclamation and Enforcement
Brooks Towers
1020 15th Street
Denver, Colorado 80202

Dear Mr. Hamm:

Enclosed are the final remaining responses to your letter of Deer Creek deficiencies dated December 20, 1984. Specifically, this submittal includes:


Second Set of Deficiencies

Item 1 - Revised drawings and calculations to include energy dissipators and increased clay liner for final reconstructed stream channel across the mine pad.

Third Set (DOGM Deficiencies)

Items 1, 2 & 3 - Additional text in response to the perennial status of the streams and responses to buffer zones and subsidence.

Yours truly,



C. E. Shingleton
Director of Permitting,
Compliance & Services
Mining and Exploration

CES:WCM:bb:4705
Enclosure

cc: Ron Daniels, DOGM
George Cotton, Simons & Li