



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0019

file

John

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 7/22/87; 12:00 am

Permittee and/or Operators Name: Utah Power and Light Mining Company
 Business Address: P.O. Box 310 Huntington, Utah 84528
 Mine Name: Deer Creek Permit Number: ACT/015/018
 Type of Mining Activity: Underground Surface Other
 County: Emery
 Company Official (s): Val Payne, Ray Christianson
 State Official(s): Kathryn Mutz, Tom Munson, Harold Sandbeck
 Partial: Complete: Date of Last Inspection: 6/18/87
 Weather Conditions: Sunny and warm
 Acreage: Permitted 14602 Disturbed 26.5 Regraded Seeded Bonded 26.5
 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	(X)
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION 7/22/87

(Comments are Numbered to Correspond with Topics Listed Above)

- 4d. Straw bales and silt fences along the conveyor were still functioning but several were filling with sediment. Routine maintenance will be performed on them by August 1, 1987.

The silt fence/straw bale 'pond' near the ClC2 transfer rollover will need fabric replacement in the near future. At that time the operator will move it a few yards down the road so that it has greater capacity and so that water does not pond below the structure.

8. The non-coal waste bins and conveyor trash picking area appear to have been cleaned/straightened up recently. Miscellaneous non-coal waste scattered in culvert grates, near the double culvert west of the non-coal waste bin and around the site will be cleaned up before the August inspection.
17. Minor spillage at the ClC2 transfer rollover was cleaned up since the last inspection.

Copy of this Report:

Mailed to: Donna Griffin (OSM), Val Payne (UP&L)

Given to: Joe Helfrich, John Whitehead

Inspectors Signature and Number: *Kathryn Metz* #21 Date: 7/22/87