

0011



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

pgl jch

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 9, 1991
2:00 p.m. to 4:25 p.m.

Permittee and/or Operators Name: PacifiCorp Electric Operations
Business Address: 210 S Main, Suite 2100, SLC, UT 84140-0021
Mine Name: East Mountain Exploration Permit Number: ACT/015/018-91B
Type of Mining Activity: Underground X Surface Other
County: Emery
Company Official (s): None
State Official(s): Ken Wyatt, Tom Munson
Partial: X Complete: Date of Last Inspection: NA
Weather Conditions: Clear and warm
Acreage: 2.7 Permitted 2.7 Disturbed Regraded Seeded Bonded
Enforcement action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	(X)
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 10/9/91

(Comments are Numbered to Correspond with Topics Listed Above)

Exploration activities on East Mountain in 1991 include two coal exploration drill holes permitted as a minor exploration activity. These include holes EM-66 and EM-148.

EM-148 was completed at the time of this inspection. It included placing a coaxial cable down the hole and cementing it in place to study subsidence and shear stressing of the rock strata following longwall mining. Re-grading and revegetation of the drill pad was complete.

EM-66 was not drilled at this time. During the inspection the drill pad had just been graded and the access road was being graded.

3. TOPSOIL

Topsoil at EM-66 had been segregated above the pad.

11. CONTEMPORANEOUS RECLAMATION

The pad associated with EM-148 had been reclaimed. The topography was acceptable and seed was observed on the pad surface.

13. REVEGETATION

Seed was observed on the surface of EM-148. Since EM-148 is a research facility, the access road is needed for another year, therefore the road was not regraded and seeded.

16a. ROAD: CONSTRUCTION

The access road to EM-66 was being graded at the time of the inspection. A primitive road existed in this area. A dozer was regrading the surface of the road to create better access by the drill rig. The operator of the dozer said that they would be moving the drill rig in as soon as they finished working on Trail Mountain.

The access road to EM-148 was not reclaimed. The applicant intends to maintain access to this site until 1993 after monitoring is completed.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Blake Webster & Guy Davis (PEO)

Given to: Joe Helfrich (DOGM)

Inspectors Signature: _____

Ken Wyatt

~~#42~~
7

Date: 10/28/91